

<i>Parameter</i>	<i>Conditions</i>	<i>Min</i>	<i>Typ</i>	<i>Max</i>	<i>Unité</i>
Resolution			0.1		mbar
Absolute pressure accuracy	p = 750 ... 1100mbar Ta = 25°C	-1.5		+1.5	mbar
Absolute pressure accuracy	P = 750 ... 1100 mbar	-0.5		+0.5	mbar
Error over temperature	Ta = 0 .. +70°C p = const.	-2		2	mbar
Long term stability	12 months		-1		mbar

Pressure sensor is an Intersema MS5534